



## Client Checklist

This checklist shows you what XEDI needs to start working with you **if your project planning is beyond the idea stage.**

- If you have a **System block diagram only**, you have come to XEDI in the **Architecture phase**.

**At end of phase, you will have:**

- Block diagram of electrical design

For the **Schematic Phase**, please provide:

- Block diagram showing major components of design
- List of all interfaces from electrical board to customer equipment including:
  - Manufacturer part numbers
  - Electrical properties (voltages, currents, signal levels)

**At end of phase, you will have:**

- Schematics and netlist
- Bill of Materials (BOM)

For the **Layout phase**, you need to provide:

- Schematic and BOM if in OrCAD
- Netlist, BOM and .pdf version of schematic if not in OrCAD
- Board outline in 1:1 .dxf format, or step file or measured drawing

**At end of phase, XEDI will provide:**

- Complete set of Gerber files
- Necessary documentation
- Board file
- Optional outputs:
  - .dxf, .idf and/or step files
  - ipc 356 netlist